THIS DOCUMENT COULD NOT BE AUTHENTICATED AND HAS BEEN PLACED IN THE FILE FOR HISTORICAL PURPOSES ONLY DATE 10/23/90

	INITIAL A	SSESSMEN	T FORM	1			
I. SITE NAME AND LOCAT	ΓΙΟΝ						
01 SITE NAME CFA-674 Excess Yard	- Lead Spil	1		02 ADDI Idaho Labora	Natio	onal Engi	neering
03 CITY	0	4 STATE	05 Z	P CODE	06 CC	UNTY	
Scoville 09 COORDINATES: NORTH	EAST	<u> Idaho</u>	07.00	NINTY C		itte B CONG. D	ICT
			07 ((JUNIT CO	שני שני שני	S CUNG. D	151.
67810	_	7 4 0					
10 DIRECTIONS TO SITE US 20 to INEL Portlan	(Starting front of the CF)	om neare: A	st pul	olic roa	ad)		
II. OWNER/OPERATOR		-					
01 OWNER (If known)		02 STRE	ET ADI	ORESS			
Department of Energy	(DOE)	785	DOE P	lace	n=155	TEL EBUAL	E MIMBER
03 CITY		04 STATI	E 05	ZIP COL	DE 06	TELEPHON	E NUMBER
Idaho Falls O7 OPERATOR (If known)		<u>Idaho</u> 08 STRE	_ <u>{</u> ET ADI	33402 DRESS	l	(208) 52	6-1122
EG&G Idaho, Inc.		P. 0.					
09 CITY	·	10 STAT	E 11	ZIP COL	DE 12	TELEPHON	E NUMBER
Idaho Falls		Idaho	8	33415		(208) 52	6-1014
III. CHARACTERIZATION (OF POTENTIAL	HAZARD			•		
01 ON SITE INSPECTION	x YES	NO	DATI	<u> 02/08</u>	8/89	_	
02 SITE STATUS (Check	one)			03 '	YEARS	RECEIVED	HAZ WASTE
<u>x</u> A. Active SWMU	_ B. Inactiv	e C.	Unkno			1988	·
04 DESCRIPTION OF SUBS See Waste Information		BLY PRES	ENT, I		art OR ALL	Stop EGED	Unknown
05 DESCRIPTION OF POTE	NTIAL HAZARD	TO ENVI	RONMEI	NT AND/	OR POP	PULATION	
See Hazardous Condi	tions and In	cidents	Section	on			
IV. INFORMATION AVAILA	BLE FROM						
01 CONTACT	02 OF (Agen	cy/Org.)		0:	3 TELE	PHONE NU	IMBER
Clifford Clark	DOE-		T	_		526-112	
04 PERSON RESPONSIBLE FOR ASSESSMENT	05 AGE	NCY	06 01	≺G.	07	TELEPHONE	. NUMBER
W. R. Pigott 08 DATE	EG&G	Idaho	ERP		(208	3) 526-24	42
02/08/89 Mon Day Year							
i rion bay rear							

		WASTE	INFORM	ATION		
I. WASTE S	TATES, QUANTITI	ES, AND C	HARACTE	RISTICS		
X A. Solid B. Powder C. Sludge D. Other	STATES (Check aE. Sluck FinesF. LickG. Gas	urry quid S		LB: TOI CUI NO	S <u>10 this</u> NS BIC YARDS . OF DRUMSJK tileL	s incident
II. WASTE	TYPE			·	1	
SLU OLW SOL PSD OCC IOC ACD BAS	SUBSTANCE NAME Sludge Oily Waste Solvents Pesticides Other organic chemic Acids Bases	nemicals cals		S AMOUNT	O2 UNIT	COMMENTS
MES	Heavy metals		1	0	Lbs	Lead
O1 CATEGORY	OUS SUBSTANCE NAME Lead	AND CONST 03 CAS NUMBE	04	N.O.S. STOR/DISIMETHOD	P 05 CONG	C. O6 MEASURE
	S OF INFORMATION		e title	s, sample	analysis	reports,etc.) pratory records.
Site inspe	ections, personne	: interv	iews, p	rocess re	cords, labo	oratory records.

I

į

[HAZARDOUS CONDITIONS AND INCIDENTS
I.	HAZARDOUS CONDITIONS AND INCIDENTS
	A. GROUNDWATER CONT.
	B. SURFACE WATER CONT. O2 OBSERVED (Date) POTENTIAL NARRATIVE DESCRIPTION: ALLEGED N/A
01	C. CONTAMINATION OF AIRO2 OBSERVED (Date) POTENTIAL POULATION POTENTIALLY AFFECTED O4 NARRATIVE DESCRIPTION ALLEGED N/A
01	D. FIRE/EXPLOSIVE CONDITIONS OBSERVED (Date) POTENTIA POPULATION POTENTIALLY AFFECTED O4 NARRATIVE DESCRIPTION ALLEGED N/A
01	E. DIRECT CONTACT O2OBSERVED (Date)POTENTIAL POPULATION POTENTIALLY AFFECTEDO4 NARRATIVE DESCRIPTIONALLEGED N/A
03	\underline{x} F. CONTAMINATION OF SOIL 02 \underline{x} OBSERVED (Date $\underline{2/3/88}$) POTENTIAL NARRATIVE DESCRIPTION: \underline{x} ALLEGED A spill response form was completed on this incident. Molten lead was spilled on the ground by a private contractor during a cutting operation. The area was cleaned up, however, a sampling of the area indicates there is lead in the soil above threshold level.
	G. DRINKING WATER CONTAMINATION 02 OBSERVED (Date) POTENTIAL NARRATIVE DESCRIPTION: ALLEGED N/A

	HAZARDOUS CONDITIONS AND INCIDENTS
I.	HAZARDOUS CONDITIONS AND INCIDENTS (Continued)
	_ J. DAMAGE TO FLORA
i	_ K. DAMAGE TO FAUNA O2 OBSERVED (Date) POTENTIAL ARRATIVE DESCRIPTION: (include name(s) of species) ALLEGED
04 N	_ L. CONTAMINATION OF FOOD CHAIN O2 OBSERVED (Date) POTENTIAL ARRATIVE DESCRIPTION: ALLEGED
(SPI 03 N	M. UNSTABLE CONTAINMENT OF WASTES 02 OBSERVED (Date)POTENTIAL LL RUNOFF, STANDING LIQUIDS/LEAKING DRUMS) ARRATIVE DESCRIPTION: ALLEGED /A
	_N. DAMAGE TO OFFSITE PROPERTY O2 OBSERVED (Date) POTENTIAL ARRATIVE DESCRIPTION: ALLEGED
04 N	_ O. CONTAMINATION OF SEWERS,STORM O2 OBSERVED(Date) POTENTIAL DRAINS, WWTPS ARRATIVE DESCRIPTION: ALLEGED /A
04 N	P. ILLEGAL/UNAUTHORIZED DUMPING 02 OBSERVED (Date) POTENTIAL ARRATIVE DESCRIPTION: ALLEGED
05 D	ESCRIPTION OF ANY OTHER KNOWN, POTENTIAL OR ALLEGED HAZARDS
III.	COMMENTS
Site Inst	SOURCES OF INFORMATION (List specific references, e.g., state titles, sample analysis, reports) inspections, personnel interview, disposal quantity records, EG&G-WM-6875 allation Assessment Report, USGS Report IDO-22053 TIC-4500 The Influence iquid Waste Disposal on the Geochemistry of Water at the NRTS.

PRIORITY RANKING SYSTEM
I. GENERAL FACILITY INFORMATION
FACILITY NAME: CFA-674 Excess Yard Lead Spill
LOCATION: INEL
POINT OF CONTACT: NAME: F. Hunter Weiler
ADDRESS: DOE-ID, Scoville, ID
PHONE: 208-526-0601
REVIEWER: W. R. Pigott DATE: 2/10/89
II. GENERAL FACILITY DESCRIPTION
GENERAL DESCRIPTION OF THE FACILITY: (For example: landfill, surface impoundment, pile, container; types of hazardous substances; location of facility; contamination route of major concern; types of information needed for rating; agency action, etc.) A private contractor was removing scrap from the excess yard. One vessel was too large
for his truck. The contractor decided to cut the tank into smaller pieces. After
cutting through the outer layer, a lead lining was encountered. The contractor laid
metal sheeting around the tank to contain the molten lead. In the process, lead was
deposited on the ground. For additional details, see Critique Report CR 88-6 and
letters PDR-6-88, SJS-7-88.
III. SCORES
SM = 2.2 (Sgw= 9.7 Ssw= 4.8 Sa= 0)
SFE = <u>0</u>
spc - 0

RATING FACTOR	ASSIGNED VALUE (Circle one)	MULTI- PLIER	SCORE	MAX. SCORE	REF. Section
		<u> </u>	<u>.l</u>	1	3.2
1 Dollman out na omna	T007.00				
1.ROUTE CHARACTER Depth to Aquifer Concern		2	0	6	
Net Precipitatio	n (0) 1 2 3	1	0	3	
Permeability of Unsaturated Zo		1	2	3	
Physical State	0 1 2 3	1	1	3	
Total	Route Characteristics Score		3	15	
2.CONTAINMENT	0 1 (2) 3	1	2	3	3.3
3.WASTE CHARACTER	ISTICS	<u>, </u>			3.4
Toxicity/Persist			18	18	
azardous Waste Quantity	0 🕕 2 3 4 5 6 7 8	1	1	8	
Total	Waste Characteristics Score		19	26	
4. Multiply lin	es 1 x 2 x 3		114	1170	
			. 1		<u> </u>
				1	

.

	SURFACE WATER ROUTE WOR	KSHEET	т		·····
RATING FACTOR	ASSIGNED VALUE (Circle one)	MULTI- PLIER	SCORE	MAX. SCORE	REF. Section
			<u> </u>		4.2
1.ROUTE CHARACTERISTICS Facility Slope and	6 6 123	1	0	3	
Intervening Terrain 1-yr. 24-hr. Rainfall Distance to Nearest Surface Water	1 2 31 2 3	1 2	0 0	3 6	
Physical State	0 1 2 3	1	1	3	
Total Route	e Characteristics Score		1	15	
2.CONTAINMENT	0 1 2 3	1	3	3	4.3
3.WASTE CHARACTERISTICS Toxicity/Persistence azardous Waste Quantity	0 3 6 9 12 15 (18) 0 1) 2 3 4 5 6 7 8	1		18	4.4
Total Waste	Characteristics Score		19	26	
4. Multiply lines 1	x 2 x 3		57	1170	
5. Divide line 4 by 1	170 and multiply by 100	Ssw=	4.8	į	

÷. • .

		AIR ROUTE WORKSHE	ET	1		
RATING	FACTOR	ASSIGNED VALUE (Circle one)	MULTI- PLIER	SCORE	MAX. SCORE	REF. Section
1.HISTORIC	RELEASE	0 45	1	0	45	5.1
Date and	Location: S	ee attached supplement	pages			
If line 1	is 0, the Sa	= 0. Enter on line 5				
If line 1	is 45, then	proceed to line 2.				
2.WASTE CHA Reactivity Incompat	and	0 1 2 3	1		3	5.2
Toxicity Hazardous Quantity	- Waste	0 1 2 3 0 1 2 3 4 5 6 7 8	3 1		9 8	
	Total Waste C	haracteristics Score	······································		20	
TARGETS Population 4-mile R		0 9 12 15 18 21 24	1		30	5.3
	o Sensitive	27 30 0 1 2 3	2		6	
Land Tse		0 1 2 3	1		3	
	Total Target	Scores			39	
4. Kultip	ly lines 1 x	2 x 3			35100	

5. Divide line 4 by 35100 and multiply by 100 Sa =

	s	s s
ROUNDWATER ROUTE SCORE (Sgw)	9.7	3.1
SURFACE WATER ROUTE SCORE (Ssw)	4.8	2.1
AIR ROUTE SCORE (Sa)	0	0
2 2 2 Sgw + Ssw + Sa		14.5
2 2 2 SQR(Sgw + Ssw + Sa)		3.8
2 2 2 SQR(Sgw + Ssw + Sa)/1.73 = SM		2.2

DOCUMENTATION RECORDS FOR HAZARD RANKING SYSTEM

INSTRUCTIONS: As briefly as possible, summarize the information you used to assign the score for each factor (e.g., "Waste quantity = 4,230 drums plus 800 cubic yards of sludges"). The source of information should be provided for each entry and should be a bibliographic-type reference. Include the location of the document.

FACILITY NAME: CFA-674 Excess Yard Lead Spill	
LOCATION: INEL	
DATE SCORED: 2/10/89	
FIFSON SCORING: W. R. Pigott	·
FRIMARY SOURCE(S) OF INFORMATION:	
Personal interviews - site visit	1
FACTORS NOT SCORED DUE TO INSUFFICIENT INFORMATION:	
COMMENTS OR QUALIFICATIONS:	

See attached notes.

GROUNDWATER ROUTE

OBSERVED RELEASE - Undertake Corrective Action Contaminants detected (3 maximum):

Rationale for attributing the contaminants to the facility:

A contractor was observed cutting lead with a torch.

2. ROUTE CHARACTERISTICS

Lead

Depth to Aquifer of Concern

Name/description of aquifer(s) of concern:

Snake River

Depth(s) from the ground surface to the highest seasonal level of the saturated zone [water table(s)] of the aquifer of concern:

Approximately 500 ft

Depth from the ground surface to the lowest point of waste disposal/storage:

0 ft

Net Precipitation

Mear annual or seasonal precipitation (list months for seasonal):
9.07 inches

Mean annual lake or seasonal evaporation (list months for seasonal):

36 inches

Net precipitation (subtract the above figures):

- 26.93 inches

Perreability of Unsaturated Zone

Scil type in unsaturated zone:

An interbedded sequence of basaltic lava flows and sedimentary deposits.

Permeability associated with soil type:

 10^{-7} to 10^{-3} cm/sec

Physical State

Physical state of substances at time of disposal (or at present time for generated gases):

Liquid - molten lead

3. CONTAINMENT

Containment

Method(s) of waste or leachate containment evaluated:
Molten lead solidified on the ground.

Method of highest score: Same as above.

4. WASTE CHARACTERISTICS

Toxicity and Persistence

Compound(s) evaluated:
 Lead

Compound with highest score:

Lead

Hazardous Waste Quantity

Total quantity of hazardous substances at the facility, excluding thos with a containment score of 0 (Give a reasonable estimate even if quantity is above maximum):

Amount listed is the known amount. The amount could be higher if the problem is wide-spread in the excess yard.

Basis of estimating and/or computing waste quantity:

Amount noted from the spill.

Checklist for Groundwater Releases

Tric	_+	ing Re	nloaco	<u>Yes</u>	No
1.	_		for Groundwater Releases from the Unit		
••	0		type and design		
	Ü	-	Does the unit type (e.g., land-based) indicate the potential for release?	· · · · · · · · · · · · · · · · · · ·	X
		-	Does the unit have engineered structures (e.g., liners, leachate collection systems, proper construction materials) designed to prevent releases to groundwater?	-	Х
	0	Unit	operation		
		-	Does the unit's age (e.g., old unit) or operating status (e.g., inactive, active) indicate the potential for release?	<u></u> .	<u>x</u>
		-	Does the unit have poor operating procedures that increase the potential for release?		<u>x</u>
		-	Does the unit have compliance problems that indicate the potential for a release to groundwater?		<u>x</u>
	0	Phys	ical condition		
		-	Does the unit's physical condition indicate the potential for release (e.g., lack of structural integrity, deteriorating liners, etc.)?	<i>i</i>	<u>x</u>
	0	Loca	tional characteristics		
		-	Is the unit located on permeable soil so the release could migrate through the unsaturated soil zone?	<u> </u>	<u>x</u>
		-	Is the unit located in an arid area where the soil is less saturated and therefore a release has less potential for downward migration?	X	-
		-	Does the depth from the unit to the uppermost aquifer indicate the potential for release?		X

	•		Checklist for Groundwater Releases	<u>Yes</u>	<u>No</u>
		-	Does the rate of groundwater flow greatly inhibit the migration of a release from the facility?	<u>x</u>	
		-	Is the facility located in an area that recharges surface water?		<u>X</u>
	0	Waste -	characteristics Does the waste in the unit exhibit high or moderate characteristics of mobility (e.g., tendency not to sorb soil particles or organic matter in the unsaturated zone)?		<u>x</u> _
		-	Does the waste exhibit high or moderate levels of toxicity?	<u>x</u>	····
2.	Evide O		of Groundwater Releases ting groundwater monitoring systems		
		-	Is there an existing system?		<u>X</u>
		_	Is the system adequate?		<u>x</u>
		-	Are there recent analytical data that indicate a release?		<u>x</u>
	0	Other	revidence of groundwater releases Is there evidence of contamination around the unit (e.g., discolored soils, lack of or stressed vegetation) that indicates the potential for a release to groundwater?		<u>x</u>
		-	Does local well water or spring water sampling data indicate a release from the unit?	<i>i</i>	<u>x</u>
			ne Relative Effect of the Release on Human		
<u>неај</u> 1.			<u>Environment</u> Potential		
	0	Condi	itions that indicate potential exposure		
	٠	-	Are there drinking water well(s) located near the unit?	<u>x</u> _	
		-	Does the direction of groundwater flow in- dicate the potential for hazardous constitu- ents to migrate to drinking water wells?		<u>x _</u>

SURFACE WATER ROUTE

1. OBSERVED RELEASE - Undertake Corrective Action

Contaminants detected in surface water at the facility or downhill from it (3 maximum):

Lead

Rationale for attributing the contaminants to the facility:

See attached reports.

2. ROUTE CHARACTERISTICS

Facility Slope and Intervening Terrain

Average slope of facility in percent:

< 1%

Name/description of nearest downslope surface water:

Big Lost River

Average slope of terrain between facility and above cited surface wate body in percent:

0%

Is the facility located either totally or partially in surface water?

No

Is the facility completely surrounded by areas of high elevation?

Yes

1-year 24-Hour Rainfall in Inches

less than 2 inches

Distance to Nearest Downslope Surface Water

Approximately 2 miles

Physical State of Waste

Solid metal

3. CONTAINMENT

Containment

Method(s) of waste or leachate containment evaluated:

Intervening terrain

Method with highest score:

Same

Checklist for Surface Water/Surface Drainage Releases

				<u>Yes</u>	<u>No</u>
Ide:	ntify:	ing Re	eleases		
1.			for Surface Water/Surface Drainage Release Facility		
	•		imity to Surface Water and/or to Off-site		
		-	Could surface run-off from the unit reach the nearest downgradient surface water body?		_X_
		-	Could surface run-off from the unit reach off-site receptors (e.g., if facility is located adjacent to populated areas and no barrier exists to prevent overland surface run-off migration)?		<u>x</u>
	0	Relea	ase Migration Potential		
		-	Does the slope of the facility and intervening terrain indicate potential for release?		<u>x</u>
		-	Is the intervening terrain characterized by soils and vegetation that allow overland migration (e.g., clayey soils, and sparse vegetation)?		_X_
		-	Does data on one-year 24-hour rainfall indicate the potential for area storms to cause surface water or surface drainage contamination as a result of run-off?		_ <u>X</u> _
	0	Unit	Design and Physical Condition	· i	
		-	Are engineered features (e.g., run-off control systems) designed to prevent release from the unit?		<u>X</u>
		-	Does the operational history of the unit indicate that a release has taken place (e.g., old, closed or inactive unit, not inspected regularly, improperly maintained)?		<u> </u>
		-	Does the physical condition of the unit indicate that releases may have occurred (e.g., cracks or stress factures in tanks or erosion of earthen dikes of surface impoundments)?		<u>x</u>

Checklist for Surface Water/Surface Drainage Releases

			<u>Yes</u>	<u>No</u>
	0	Waste Characteristics		
		Is the volume of discharge high relative to the size and flow rate of the surface water body?		<u>x</u>
		Do constituents in the discharge tend to sorb to sediments (e.g., metals)?	<u>x</u>	
		Do constituents in the discharge tend to be transported downstream?		<u>x</u>
		Do waste constituents exhibit moderate or high characteristics of persistence (e.g., PCBs, dioxins, etc.)?	<u> </u>	
		Do waste constituents exhibit moderate or high characteristics of toxicity (e.g., metals, chlorinated pesticides, etc.)?	<u>x</u>	
2.	Evid	dence of Surface Water/Surface Drainage Releases		
	0	Are there unpermitted discharges from the facility to surface water that require an NPDES or a Section 404 permit?		<u>x</u>
	0	Is there visible evidence of uncontrolled run-off from units at the facility?		<u>x</u>
		ning the Relative Effect of the Release on Human and the Environment	i i	
1.	0	Are there drinking water intakes nearby?	<u>x</u> _	
	0	Could human and/or environmental receptors come into contact with surface drainage from the facility?		х
	0	Are there irrigation water intakes nearby?		X
	0	Could a sensitive environment (e.g., critical habitat, wetlands) be affected by the discharge (if it is nearby)?		X

AIR ROUTE

1.	OBSERVED RELEASE	
	Contaminants detected:	
	Unknown	
	Date and Location of detection of contaminants:	
	Methods used to detect the contaminants:	
	Rationale for attributing the contaminants to the site:	
		,
2.	WASTE CHARACTERISTICS	į
	Reactivity and Incompatibility	,
	Most reactive compound:	
	Most incompatible pair of compounds:	

Toxicity

Most toxic compound:

Hazardous Waste Quantity

Total quantity of hazardous waste:

Basis of estimating and/or computing waste quantity:

Checklist for Air Releases

1 do-	+ i fu:	ina P	eleases	<u>Yes</u>	<u>No</u>
1.		ntial	for Air Releases from the Facility Characteristics		
		-	Is the unit operating and does is expose waste to the atmosphere?		<u>x</u>
		-	Does the size of the unit (e.g., depth and surface area) create a potential for air release?		<u>x</u>
	0		the unit contain waste that exhibits a rate or high potential for vapor phase ase?		
		-	Does the unit contain hazardous constituents of concern as vapor releases?		<u>x</u>
		-	Do waste constituents have a high potential for volatilization (e.g., physical form, concentrations, and constituent-specific physical and chemical parameters that contribute to volatilization)?	· —	<u>x</u>
	0	condi	the unit contain waste and exhibit site itions that suggest a moderate or high atial for particulate release?		
		-	Does the unit contain hazardous constituents of concern as particulate releases?		X
		-	Do constituents of concern as particulate releases (e.g., smaller, inhalable particulates) have potential for release via wind erosion, reentrainment by moving vehicles, or operational activities?	; ;	<u>x_</u>
		-	Are particulate releases comprised of small particles that tend to travel off-site?		<u>x</u> _
			rtain environmental and geographic factors the concentrations of airborne contaminants	?	
			Do atmospheric/geographic conditions limit constituent dispersion (e.g., areas with atmospheric conditions that result in inversions)?		X
		-		<u> </u>	

Checklist for Air Releases

			<u>Yes</u>	No
2.	Evide	ence of Air Releases		
	0	Does on-site monitoring data show that releases have occurred or are occurring (e.g., OSHA data)?		<u>x_</u>
	0	Have particulate emissions been observed at the site?		x
	0	Have there been citizen complaints concerning odors or observed particulate emissions from the site?		x
		ing the Relative Effect of the Release on Human		
1.	Expos	sure Potential		
	0	Is a populated area located near the site? INEL site workers only.	X	

Checklist for Subsurface Gas Peleases

			<u>Yes</u>	МО
<u>Ide</u> :	ntify	ing a Release		
1.	Poter	ntial for Subsurface Gas Releases		
	0	Does the unit contain waste that generates methane or generates volatile constituents that may be carried by methane (e.g., decomposable refuse/volatile organic wastes)?	N/A 	<u>x</u>
	•	Is the unit an active or closed landfill or a unit closed as a landfill (e.g., surface impoundments and waste piles)?		<u>x</u>
2.		ation of Subsurface Gas to On-site or Off-site dings		
	0	Are on-site or off-site buildings close to the unit?	<u>x</u> _	
	0	Do natural or engineered barriers prevent gas migration from the unit to on-site or off-site buildings (e.g., low soil permeability and porosity hydrogeologic barriers/liners, slurry walls, gas control systems)?	<u> N/A</u>	
	0	Do natural site characteristics or man-rade structures (e.g., underground power trans-mission lines, sewer pipes/sand and gravel lenses) facilitate gas migration from the unit to buildings?		<u>x</u>
		ing the Relative Effect of the Release on Human	i	
1.	Expo	sure Potential		
	0	Does building usage (e.g., residential, commercial) exhibit high potential for exposure?	<u> </u>	.x

FIRE AND EXPLOSION

1.	CONTAINMENT	
	Hazardous substances present:	
		N/A
	Type of containment, if applicable:	
_		
2.	WASTE CHARACTERISTICS	N/A
	Direct Evidence	
	Type of instrument and measurements:	
		.
	<u>Ignitability</u>	
	Compound used:	N/A
		į
	Reactivity	
	Most reactive compound:	
	<u>Incompatibility</u>	

Most incompatible pair of compounds:

Hazardous Waste Quantity
Total quantity of hazardous substances at the facility: N/A

Basis of estimating and/or computing waste quantity:

3. TARGETS <u>Distance to Nearest Population</u>

Approximately 100 ft

<u>Distance to Nearest Building</u>
Approximately 100 ft

Distance to Sensitive Environment

Distance to wetlands: Greater than 100 ft

Distance to critical habitat:
Greater than 1/2 mile

Land Use

Distance to commercial/industrial area, if 1 mile or less:

Greater than 1 mile

Distance to national or state park, forest, or wildlife reserve, if 2 miles or less:

Greater than 2 miles

Distance to residential area, if 2 miles or less: Greater than 2 miles

Distance to agricultural land in production within past 3 years, if 1 mile or less:

Greater than 1 mile

Distance to prima agricultural land in production within past 3 years, if 2 miles or less:

Greater than 2 miles

If a historic or landmark site (National Register or Historic Places and National Natural Landmarks) within the view of the site?

Big Southern Butte

Population Within 2-Mile Radius

Approximately 1500 site workers

Buildings Within 2-Mile Radius

42

DIRECT CONTACT

1. OBSERVED INCIDENT

Date, location, and pertinent details of incident:
None

2. ACCESSIBILITY

Describe type of barrier(s): Fenced area with limited access

3. CONTAINMENT

Type of containment, if applicable:
None

4. WASTE CHARACTERISTICS

Toxicity

Compounds evaluated:

Lead

Compound with highest score:

Lead

5. TARGETS

Population within one-mile radius

Approximately 1500 site workers

Distance to critical habitat (of endangered species)

Greater than 2 miles

2/7/89

Telecon

John Fox 2612

At the time the lead spill was identified, there was approximately 1# of lead on the ground. The ground was frozen at the time and the contractor had metal panels on the ground. The lead found in the soil could go back as far as the Navy days. The extent of the lead in the Excess Yard is unknown.

Jay White 2613

The lead spill area referenced above is just inside the gate (see attached sketch). The attached report shows the lead is in a wider area and deeper than anticipated. The old section of the Excess Yard was used by the Navy in the 1940s. There is no information available on what it was used for during that period. The sketch shows the old battery storage area and an area for excess lead. Scrap possibly containing lead was stored in other areas of the Excess Yard. The potential exists for finding lead almost anywhere in the yard. Lead is currently not stored in these areas. The Excess Yard is still used for excessing other materials.

Extension added approx.	ded approx. 1978	Original yard used by the Navy, approx. 1940s
		(There is the possibility that lead could be found in the soil anywhere in this yard since earlier practices are unknown)
	<pre>< Lead for excess stored in this area at one period of time</pre>	
	01d battery storage area	Lead spill during scrap cutting by contractor

2/8/89 W. R. Pigott info from Jay White

CFA-674



SPILL RESPONSE FORM

Name of Reporting OfficialJohn E. Fox	Phone #526-2612
Responsible Company Name and Address <u>EG&G Idaho, Inc.</u>	, P.O. Box 1625, Property Management
CFA-614, Idaho Falls, ID 83415-4135	
Date and Time Discharge Noted February 3, 1988. Approx	ximately 3:00 p.m.
Location of Discharge: State, County, Facility Name, and Street Addres	s Idaho, Butte County,
Idaho National Engineering Laboratory, CFA-674, Ex	
Type of Material Discharged Molten lead and lead fumes	
Source, Cause, and Amount of Discharge Lead lined cask,	cutting torch,
Lead splattering on ground approximately 10 pound	s/vapor release unknown.
Amount of Material Spilled into Water None	
Weather Conditions Clear and cold (approximately 20	°F)
None	
None annarent	
Continuing Danger to Health or Environment None apparent	11-12-06-48-5-06-1-1-1
Description of Remedial Action Immediate area to be clevessel removed from INEL.	aned of lead drippings and the
If Transportation Related:	
Name of Carrier	
Railcar number, truck number or vessel name	
Name of shipper	
Name of Consignee	
Reporting:	
Name of Person Reported to at DOE-IDC. A. Anderson	, Environmental Compliance
Date and time reported to DOE-ID <u>February 4, 1988,</u>	approximately 10:30 a.m.
Other persons/groups notified W. J. Harrie, Industr	ial Safety Branch
Other pertinent information	

cc: Area Landlord ES&C, CFA 612 1. Critique Report No.: CR88-6 Issue Date: February 8, 1988

2. Critique Meeting Date: February 5, 1988 Time: 1:00 p.m.

3. Unusual or Unplanned Event Subject:

Molten lead spill and lead vapor release as a result of cutting torch being used on a lead-lined cask.

- 4. Date of Event: February 3, 1988 Time of Event: 3:00 p.m.
- 5. Facility, System, or Equipment:

Lead lined vessel located in Excess Yard at CFA-674 cut for size reduction by a cutting torch.

6. Organization Involved:

Private Off-Site Business (Frontier Car Corral) and EG&G Idaho, Inc., Property Management.

7. Apparent Cause Categories:

- () Design () Material (X) Personnel () Procedure () System () Equipment (X) Process () Other
- 8. Description of Event:

A private contractor who had successfully bid for a quantity of surplus scrap metal was On-Site at the EG&G Excess Yard (CFA-674) on Wednesday, February 3, 1988, to remove the metal. In the course of this removal, the contractor determined that a vessel contained in this scrap lot would have to be cut up to enable removal. After cutting through the outer layer of the vessel, a lead lining was encountered. The contractor laid metal sheeting around the base of the vessel to contain lead drippings and continued to cut through the lead. At approximately 2:30 p.m. an EG&G Sr. Engineer (Richard C. Green) drove past the vessel location and observed the lead cutting process and a Safety Representative (Delwin J. Allred) was immediately contacted.

A visit to the location by the Safety Representative disclosed that proper precautions were not being followed resulting in lead drippings on the ground and lead vapor being released into the atmosphere. It was also determined that the contractor had not received prior Safety approval

8. Description of Event (Cont'd.):

to use a cutting torch as required in the EG&G Conditions of Sale. The contractor was directed to stop the cutting operation pending a review of the situation. The Excess Yard was locked for the day and the immediate cutting area cordoned off on Thursday, February 4, 1988.

9. Apparent Cause:

The private contractor did not request Safety approval prior to the cutting operation resulting in his cutting into the lead lined vessel without appropriate Safety Reviews.

10. Immediate Corrective Action Taken and Further Corrective Actions Required:

The cutting operation was terminated pending a Safety Critique and the Excess Yard locked on Wednesday, February 3, 1988. The following day the vessel location was cordoned off and the Excess Yard opened for routine business. Pre and post cleanup samples will be taken and EP-Tox Test results made available. In addition, a Spill Response Form has been prepared.

Further corrective actions being considered are: (1) A sign will be posted at the entrance to the EG&G Excess Yard stating that "All Cutting Operations Are Prohibited Without Prior Approval", (2) The current EG&G Surplus Sales Agreements will be modified to ensure specific bidder acknowledgment of scrap metal cutting restriction prior to scrap metal bid award releases. Organizational responsibilities related to identification and handling of potentially hazardous scrap materials will be clarified.

- 11. Meeting Attendance List Attached: (X) Critique Reviewed for Potential of Similar Event Occurring in Plant
- 12. UOR is Required:
 - (X) YES (Distribute and then proceed with UOR Instructions in Safety Manual Supplement 3.2)

()	NO	(Proceed	with	the	Corrective	Actions	and	Distribution)
Basi	s:							

13.	Signatures:		
	Critique Leader: The Management of the Critique Leader:	Date:	2-9-88
	Title: Support Services Group Manager	Dept:	Administration
	Operations Manager: LE 7-x	Date:	2/9/88
	Title: Marayer, Property Management	Dept:	administrate

Attachment to CR88-6 February 8, 1988 Page 1

ATTENDANCE LIST CRITIQUE REPORT NO. CR88-6

NAME	ORGANIZATION	PHONE
D. E. Ardary	EG&G CFA Industrial Hygiene	6-2756
E. R. Summers	EG&G CFA Landlord Office	6-2492
W. H. Bodily	EG&G Environemntal Compliance	6-2360
M. R. Carroll	EG&G Materiel Services	6-2421
L. D. Andersen	EG&G Property Management	6-2440
J. E. Fox	EG&G Property Management	6-2612
J. E. White	EG&G Property Management	6-2613
C. D. Jackson	EG&G Safety	6-4381
R. C. Green	EG&G Safety	6-2702
K. Stanger	Support Services	6-0668